



Tech Info Library

High Speed Serial Interface: Manual Errata (11/96)

Revised: 11/21/96
Security: Everyone

High Speed Serial Interface: Manual Errata (11/96)

Article Created: 21 September 1984
Article Reviewed/Updated: 19 November 1996

TOPIC -----

Listed below are corrections to the High Speed Serial Interface manual
(030-0012-00).

DISCUSSION -----

Corrections
=====

Page 16

The information for switch 4 is reversed, it should read:

ON = delay enabled
OFF = delay disabled

Page 32

Two labels on the schematic diagram are wrong:

XMIT		XMIT
-----O B	should be	-----O C
WIRE		WIRE
TO		TO
PIN 3		PIN 3

RECV		RECV
-----O C	should be	-----O B
WIRE		WIRE
TO		TO

PIN 2

PIN 2

P8A PROM

The P8A PROM interferes with the operation monitor routines that use \$3C. The P8A uses this location as a temporary storage space and does not restore it.

Article Change History:

19 Nov 1996 - Reviewed for technical accuracy, revised formatting.

Copyright 1984-96, Apple Computer, Inc.

Tech Info Library Article Number:529